



GARLAND INDEPENDENT SCHOOL DISTRICT

PURCHASING DEPARTMENT
501 SOUTH JUPITER ROAD
Garland, Texas 75042

March 1, 2019

ADDENDUM #1, RFP # 333-19

FIRE ALARM INSPECTIONS SERVICE AND PARTS

This addendum forms a part of the solicitation documents, modifies the original document as listed below, and is hereby made part of any pursuant award. Acknowledge receipt of this is addendum by returning the completed and signed form with the solicitation response. Failure to submit the addenda will be used as an evaluated factor.

THE DATE AND TIME FOR SUBMITTAL OF RESPONSES IS UNCHANGED

Questions and responses are on pages following.

Don Friedel
Assistant Director of Purchasing

Company Name

Address

City State Zip

Signature

Title

<p>Could you please provide device counts, points list, and or previous years' inspection reports for all of the fire alarm systems included in this RFP?</p> <p>Is there a device breakdown per building for the inspections in the form of a spreadsheet? If not, is there a previous inspection document that we can obtain to see how many devices there are per building?</p>	<p>The information Garland ISD is able to provide is in the form of sample reports following this page.</p>
<p>Can you also please answer if there is a cost and what it would be for the fingerprinting needed as part of the RFP?</p>	<p>Our fingerprinting division states the charge is currently approximately \$39 for each contracted employee performing service on Garland ISD property. This is a one-time charge associated in doing business with the District. Once a contracted employee is fingerprinted for the DPS database, the process does not have to be repeated in subsequent contract years.</p>



Flores Technical Services, Inc. dba F T S

NCTRCA D/M/WBE Certification # HMDB31312Y0707 ♦ HUB Certification #1752741251800
Security License B09038 ♦ Fire License ACR 1793 ♦ Electrical Contractors License #00052
13531 Floyd Circle Dallas, Texas 75243 (972) 792-7793 Office (972) 792-7149 Fax

FIRE ALARM INSPECTION REPORT

GISD - ClubHill Elem

10/31/2018



Flores Technical Services, Inc. dba F T S

NCTRCA D/M/WBE Certification # HMDB31312Y0707 ♦ HUB Certification #1752741251800
Security License B09038 ♦ Fire License ACR 1793 ♦ Electrical Contractors License #00052
13531 Floyd Circle Dallas, Texas 75243 (972) 792-7793 Office (972) 792-7149 Fax

FIRE ALARM INSPECTION AND TESTING FORM

Date: 10/31/2018 Time: 8:30

Client Name: GISD - Club Hill Elem Telephone: 972.926.2520

Contact Name: Keith Chapman Telephone: 972.487.4259
E-Mail: kachapma@garlandisd.net

Address: 1330 Colonial Dr.

City/State/Zip: Garland, TX 75043-1304

Test Frequency: Annual Semi-Annual _____ Quarterly _____ Other _____

Date of Last Inspection: 6/13/2016 Date of Install: 5/3/2010

Date of Last System Service: 7/12/2010

Last date that any software/configuration was revised: Unknown

Fire Alarm Panel

Area Served/Location: Office

Fire Panel Manufacturer: Harrington Model: HS3200

Upon arrival is system clear? Yes No _____

Existing tag color: White/Green _____ Blue Yellow _____ Red _____

Notifications To Be Made Prior To Testing

Building Occupants: Yes _____ No Who Contacted _____ Time _____

Monitoring Company: GISD Security Who Contacted _____ Time 8:30 PM

Phone Number: 972.487.4112 Account#: GISD

Line# 1: _____ Line# 2: _____

DACT Mfr/Model: Harrington HS3DL Location: Onboard
MDI monitors Alarm, Supervisory, Trouble per AHJ.

Solenoids Removed By: n/a

Alarm Initiating Devices and Circuit Information

	Quantity	Circuit Style
Manual Pull Station:	<u>13</u>	<u>SLC-6</u>
HPM Pull Station:	<u>0</u>	<u></u>
Ion Detector:	<u>0</u>	<u></u>
Photoelectric Detector:	<u>103</u>	<u>SLC-6</u>
Duct Detector:	<u>9</u>	<u>SLC-6</u>
Heat Detector:	<u>4</u>	<u>SLC-6</u>
Waterflow Switch:	<u>0</u>	<u></u>
Tamper Switch:	<u>0</u>	<u></u>
Supervisory Switch:	<u>0</u>	<u></u>
Control:	<u>0</u>	<u></u>
Other-Relays:	<u>0</u>	<u></u>
Other-Kitchen Hood:	<u>1</u>	<u>SLC-6</u>
Other-Beam Det:	<u>0</u>	<u></u>

Alarm Indicating Devices

	Quantity	Functional
Annunciators: (GCC)	<u>1</u>	<u>Yes</u>
Bells:	<u>0</u>	<u></u>
Horns:	<u>0</u>	<u></u>
Horn Strobes:	<u>Multi</u>	<u>Yes</u>
Strobes:	<u>Multi</u>	<u>Yes</u>
Speakers:	<u>0</u>	<u></u>
Speaker Strobes:	<u>0</u>	<u></u>
Are all circuits supervised? (Y/N)	<u>Yes</u>	<u></u>

Auxiliary Functions

	Does Device Function Properly		
	Yes	No	N/A
Dampers:	<u></u>	<u></u>	<u>X</u>
Door Holders:	<u></u>	<u></u>	<u>X</u>
Exit Lights:	<u></u>	<u></u>	<u>X</u>
HVAC:	<u>X</u>	<u></u>	<u></u>
Elevator Recall:	<u></u>	<u></u>	<u>X</u>
Mag Lock Drop Out:	<u></u>	<u></u>	<u>X</u>

Batteries

See Additional Sheets

Battery Type: Sealed Lead Acid: _____ Lead Acid: _____ Quantity: _____
 Date of Last Replacement: _____
 Battery #1 Amp-Hour Rating: _____ Volt/Amp-Hour Results: _____
 Battery #2 Amp-Hour Rating: _____ Volt/Amp-Hour Results: _____

On/Off Premises Monitoring

	Yes	No	N/A
Alarm Signal Received:	<u>X</u>	<u></u>	<u></u>
Alarm Restoral Received:	<u>X</u>	<u></u>	<u></u>
Supervisory Signal Received:	<u></u>	<u></u>	<u>X</u>
Supervisory Restoral Received:	<u></u>	<u></u>	<u>X</u>
Trouble Signal Received:	<u>X</u>	<u></u>	<u></u>
Trouble Restoral Received:	<u>X</u>	<u></u>	<u></u>

The following devices did not operate properly or did not meet current NFPA Standards:

Tested as installed. See additional sheets.

	Blue Tag	Yellow Tag	Red Tag
This system was tagged with a:	<u> X </u>	<u> </u>	<u> </u>

Solenoids Reconnected by: n/a

This system was restored to normal operation: Date 10/31/2018 Time 9:30 PM

This system was tested in accordance with all applicable NFPA Standards.

Date	<u> 10/31/2018 </u>		
Name of Inspector	<u> Martin DeAnda </u>	Signature	<u> On File </u>
License Number	<u> FAL-2081654 </u>		
Owner's Rep	<u> Keith Chapman </u>	Signature	<u> On File </u>

Signal Expander Panel Information

Panel Name/Location: FACP

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: _____ 05/11/15 Quantity: 2

Battery #1 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Panel Name/Location: FCPS #1 A/V Storage 45 L2M111

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: _____ 05/11/15 Quantity: 2

Battery #1 Amp-Hour Rating 7 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 7 Volt/Amp-Hour Results: _____

Panel Name/Location: FCPS #2 Storage Rm 48 L1M101 HPF24-S8 0 Spares

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: _____ 05/11/15 Quantity: 2

Battery #1 Amp-Hour Rating 7 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 7 Volt/Amp-Hour Results: _____

Panel Name/Location: FCPS #3 Storage Rm 48 L1M106 HPF24-S8 2 Spares

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: _____ 05/11/15 Quantity: 2

Battery #1 Amp-Hour Rating 7 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 7 Volt/Amp-Hour Results: _____

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
SMOKE DETECTOR 1-1 IN VICE PRINCIPAL OFFICE 3	Photo	1.1	PASS	
HEAT DETECTOR 1-2 IN WORKROOM 5	ThrmI	1.2	PASS	
SMOKE DETECTOR 1-3 IN PRINCIPAL OFFICE 4	Photo	1.3	PASS	
SMOKE DETECTOR 1-4 IN MAIN OFFICE 1	Photo	1.4	PASS	
SMOKE DETECTOR 1-5 IN CLINIC 2	Photo	1.5	PASS	
SMOKE DETECTOR 1-6 IN HALL BY WORKROOM 5	Photo	1.6	PASS	
SMOKE DETECTOR 1-7 IN LIBRARY 10	Photo	1.7	PASS	
SMOKE DETECTOR 1-8 IN LIBRARY 10	Photo	1.8	PASS	
SMOKE DETECTOR 1-9 IN HALL HB OUTSIDE LIBRARY 10	Photo	1.9	PASS	
SMOKE DETECTOR 1-10 IN REST ROOM 14	Photo	1.10	PASS	
SMOKE DETECTOR 1-11 IN ELECTRICALROOM 47	Photo	1.11	PASS	
SMOKE DETECTOR 1-12 ON MUSICSTAGE 11	Photo	1.12	PASS	
SMOKE DETECTOR 1-13 ON MUSICSTAGE 11	Photo	1.13	PASS	
DUCT DETECTOR 1-14 IN HALL HB OUTSIDE RESTROOM 14	Photo	1.14	PASS	
SMOKE DETECTOR 1-15 IN CAFE 12 SOUTHWEST DETECTOR	Photo	1.15	PASS	
SMOKE DETECTOR 1-16 IN CAFE 12 SOUTHEAST DETECTOR	Photo	1.16	PASS	

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
SMOKE DETECTOR 1-17 IN CAFE 12 NORTHEAST DETECTOR	Photo	1.17	PASS	
SMOKE DETECTOR 1-18 IN CAFE 12 NORTHWEST DETECTOR	Photo	1.18	PASS	
SMOKE DETECTOR 1-19 IN CAFE 12 HALL HB	Photo	1.19	PASS	
SMOKE DETECTOR 1-20 IN CLASSROOM 21	Photo	1.20	PASS	
SMOKE DETECTOR 1-21 IN CLASSROOM 20	Photo	1.21	PASS	
SMOKE DETECTOR 1-22 IN CLASSROOM 19	Photo	1.22	PASS	
SMOKE DETECTOR 1-23 IN CLASSROOM 22	Photo	1.23	PASS	
SMOKE DETECTOR 1-24 IN CLASSROOM 23	Photo	1.24	PASS	
SMOKE DETECTOR 1-25 IN CLASSROOM 24	Photo	1.25	PASS	
SMOKE DETECTOR 1-26 IN HALL H4 OUTSIDE CLASSROOM 23	Photo	1.26	PASS	
SMOKE DETECTOR 1-27 IN HALL H4 OUTSIDE CLASSROOM 24	Photo	1.27	PASS	
SMOKE DETECTOR 1-28 IN BOYS RESTROOM 33	Photo	1.28	PASS	
SMOKE DETECTOR 1-29 IN STORAGE ROOM 46	Photo	1.29	PASS	
SMOKE DETECTOR 1-30 IN GIRLS RESTROOM 34	Photo	1.30	PASS	
SMOKE DETECTOR 1-31 IN TEACHERS LOUNGE 32	Photo	1.31	PASS	
SMOKE DETECTOR 1-32 IN CLASSROOM 31 ON MUSIC-STAGE RM 4	Photo	1.32	PASS	
SMOKE DETECTOR 1-33 IN BOYS RESTROOM 84	Photo	1.33	PASS	

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
-------------	------	---------	-----------	---------

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
SMOKE DETECTOR 1-34 IN GIRLS RESTROOM 85	Photo	1.34	PASS	
SMOKE DETECTOR 1-35 IN HALL H4 BY COUNS OFFICE 29	Photo	1.35	PASS	
SMOKE DETECTOR 1-36 IN CLASSROOM 26	Photo	1.36	PASS	
SMOKE DETECTOR 1-37 IN CLASSROOM 25	Photo	1.37	PASS	
SMOKE DETECTOR 1-38 IN CLASSROOM 27	Photo	1.38	PASS	
SMOKE DETECTOR 1-39 IN CLASSROOM 28	Photo	1.39	PASS	
SMOKE DETECTOR 1-40 IN CLASSROOM 36	Photo	1.40	PASS	
SMOKE DETECTOR 1-41 IN CLASSROOM 37	Photo	1.41	PASS	
SMOKE DETECTOR 1-42 IN HALL H3 BY COUNS OFFICE 30	Photo	1.42	PASS	
SMOKE DETECTOR 1-43 IN CLASSROOM 38	Photo	1.43	PASS	
SMOKE DETECTOR 1-44 IN CLASSROOM 41	Photo	1.44	PASS	
SMOKE DETECTOR 1-45 IN CLASSROOM 42	Photo	1.45	PASS	
SMOKE DETECTOR 1-46 IN CLASSROOM 39	Photo	1.46	PASS	
SMOKE DETECTOR 1-47 IN HALL H3 OUTSIDE CLASSROOM 39	Photo	1.47	PASS	
SMOKE DETECTOR 1-48 IN CLASSROOM 40	Photo	1.48	PASS	
SMOKE DETECTOR 1-49 IN CLASSROOM 43	Photo	1.49	PASS	
SMOKE DETECTOR 1-50 IN HALL HB OUTSIDE	Photo	1.50	PASS	

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
CLINIC 2				

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
DUCT DETECTOR 1-51 IN HALL OUTSIDE COUNS OFFICES 29&30	Photo	1.51	PASS	UNIT DID SHUTDOWN
DUCT DETECTOR 1-52 IN HALL HB OUTSIDE JANITORS CLOSET 82	Photo	1.52	PASS	UNIT DID SHUTDOWN
SMOKE DETECTOR 1-53 IN STORAGE ROOM 48	Photo	1.53	PASS	
SMOKE DETECTOR 1-54 IN CLINIC RESTROOM 2	Photo	1.54	PASS	
BPS 2 TROUBLE 1-101 IN STORAGE ROOM 48	Mon	1.101	PASS	
PULL STATION 1-102 EXIT IN HALL HB BY CAFE12	Mon	1.102	PASS	
PULL STATION 1-103 EXIT IN CLASSROOM 26	Mon	1.103	PASS	
PULL STATION 1-104 EXIT IN CLASSROOM 37	Mon	1.104	PASS	
PULL STATION 1-105 AT MAIN EXIT IN HALL HB	Mon	1.105	PASS	
BPS 3 TROUBLE 1-106 IN STORAGE ROOM 48	Mon	1.106	PASS	
SMOKE DETECTOR 2-1 IN HALL HA OUTSIDE VICE PRIN OFFICE 3	Photo	2.1	PASS	
SMOKE DETECTOR 2-2 IN CLASSROOM 70	Photo	2.2	PASS	
SMOKE DETECTOR 2-3 IN CLASSROOM 73	Photo	2.3	PASS	
SMOKE DETECTOR 2-4 IN CLASSROOM 74	Photo	2.4	PASS	
SMOKE DETECTOR 2-5 IN CLASSROOM 72	Photo	2.5	PASS	
SMOKE DETECTOR 2-6 IN MDF ROOM 72-A	Photo	2.6	PASS	
SMOKE DETECTOR 2-7 IN CLASSROOM 72	Photo	2.7	PASS	

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
-------------	------	---------	-----------	---------

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
SMOKE DETECTOR 2-8 IN CLASSROOM 71	Photo	2.8	PASS	
SMOKE DETECTOR 2-9 IN HALL H7 OUTSIDE CLASSROOM 71	Photo	2.9	PASS	
SMOKE DETECTOR 2-10 IN MUSIC ROOM 65	Photo	2.10	PASS	
SMOKE DETECTOR 2-11 IN CLASSROOM 67	Photo	2.11	PASS	
SMOKE DETECTOR 2-12 IN HALL H7 OUTSIDE CLASSROOM 75	Photo	2.12	PASS	
SMOKE DETECTOR 2-13 IN CLASSROOM 63	Photo	2.13	PASS	
SMOKE DETECTOR 2-14 IN CLASSROOM 75	Photo	2.14	PASS	
SMOKE DETECTOR 2-15 IN CLASSROOM 76	Photo	2.15	PASS	
SMOKE DETECTOR 2-16 IN CLASSROOM 62	Photo	2.16	PASS	
SMOKE DETECTOR 2-17 IN CLASSROOM 61	Photo	2.17	PASS	
SMOKE DETECTOR 2-18 IN CLASSROOM 60	Photo	2.18	PASS	
SMOKE DETECTOR 2-19 IN HALL H6 OUTSIDE CLASSROOM 60	Photo	2.19	PASS	
SMOKE DETECTOR 2-20 IN CLASSROOM 66	Photo	2.20	PASS	
SMOKE DETECTOR 2-21 IN CLASSROOM 78	Photo	2.21	PASS	
SMOKE DETECTOR 2-22 IN HALL H6 OUTSIDE CLASSROOM 78	Photo	2.22	PASS	
SMOKE DETECTOR 2-23 IN GIRLS RESTROOM 64-A	Photo	2.23	PASS	
SMOKE DETECTOR 2-24 IN HALL H6 BY GIRLS	Photo	2.24	PASS	

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
RESTROOM 64-A				
SMOKE DETECTOR 2-25 IN CLASSROOM 57	Photo	2.25	PASS	
SMOKE DETECTOR 2-26 IN CLASSROOM 58	Photo	2.26	PASS	
SMOKE DETECTOR 2-27 IN CLASSROOM 59	Photo	2.27	PASS	
SMOKE DETECTOR 2-28 IN CLASSROOM 56	Photo	2.28	PASS	
SMOKE DETECTOR 2-29 IN CLASSROOM 55	Photo	2.29	PASS	
SMOKE DETECTOR 2-30 IN CLASSROOM 54	Photo	2.30	PASS	
SMOKE DETECTOR 2-31 IN HALL HA BY KITCHEN	Photo	2.31	PASS	
SMOKE DETECTOR 2-32 IN GYM SOUTHEAST DETECTOR	Photo	2.32	PASS	
SMOKE DETECTOR 2-33 IN GYM NORTHEAST DETECTOR	Photo	2.33	PASS	
SMOKE DETECTOR 2-34 IN GYM MID NORTH DETECTOR	Photo	2.34	PASS	
SMOKE DETECTOR 2-35 IN GYM MID SOUTH DETECTOR	Photo	2.35	PASS	
SMOKE DETECTOR 2-36 IN GYM SOUTHWEST DETECTOR	Photo	2.36	PASS	
DUCT DETECTOR 2-37 IN GYM EAST DETECTOR	Photo	2.37	PASS	UNIT DID SHUTDOWN
DUCT DETECTOR 2-38 IN GYM WEST DETECTOR	Photo	2.38	PASS	UNIT DID SHUTDOWN
SMOKE DETECTOR 2-39 IN GYM NORTHWEST DETECTOR	Photo	2.39	PASS	
SMOKE DETECTOR 2-40 ON MEZZ SOUTH DETECTOR	Photo	2.40	PASS	
SMOKE DETECTOR 2-41	Photo	2.41	PASS	

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
ON MEZZ NORTH DETECTOR				
SMOKE DETECTOR 2-42 IN BOYS RESTROOM 51 IN GYM	Photo	2.42	PASS	
SMOKE DETECTOR 2-43 IN GIRLS RESTROOM 52 IN GYM	Photo	2.43	PASS	
SMOKE DETECTOR 2-44 ENTRANCE TO GYM	Photo	2.44	PASS	
HEAT DETECTOR 2-45 IN KITCHEN 13	Thrml	2.45	PASS	
DUCT DETECTOR 2-46 IN KITCHEN	Photo	2.46	PASS	UNIT DID SHUTDOWN
HEAT DETECTOR 2-47 IN DISHWASH ROOM 16	Thrml	2.47	PASS	
SMOKE DETECTOR 2-48 IN KITCHEN REASTROOM	Photo	2.48	PASS	
SMOKE DETECTOR 2-49 IN MECH ROOM 18-A	Photo	2.49	PASS	
SMOKE DETECTOR 2-50 IN PANTRY 17	Photo	2.50	PASS	
HEAT DETECTOR 2-51 IN WATER HEATER CLOSET 12-B	Thrml	2.51	PASS	
SMOKE DETECTOR 2-52 IN ELECTRICAL ROOM 12-A	Photo	2.52	PASS	
SMOKE DETECTOR 2-53 IN HALL HA BY CAFE 12	Photo	2.53	PASS	
SMOKE DETECTOR 2-54 IN ELECTRICAL ROOM 60	Photo	2.54	PASS	
SMOKE DETECTOR 2-55 IN REST ROOM 15	Photo	2.55	PASS	
SMOKE DETECTOR 2-56 IN JANITORS CLOSET 47	Photo	2.56	PASS	
SMOKE DETECTOR 2-57 IN BOYS RESTROOM 68	Photo	2.57	PASS	

Club Hill Points List

Description	Type	Address	Pass/Fail	Remarks
SMOKE DETECTOR 2-58 IN HALL HA BY LIBRARY 11	Photo	2.58	PASS	
DUCT DETECTOR 2-59 IN HALL HA BY BOYS RESTROOM 68	Photo	2.59	PASS	UNIT DID SHUTDOWN
DUCT DETECTOR 2-60 IN HALL HA BY GIRLS RESTROOM 64-A	Photo	2.60	PASS	UNIT DID SHUTDOWN
DUCT DETECTOR 2-61 IN HALL OUTSIDE CLASSROOMS 66 & 67	Photo	2.61	PASS	UNIT DID SHUTDOWN
SMOKE DETECTOR 2-62 IN A/V STORAGE 45	Photo	2.62	PASS	
PULL STATION 2-101 AT MAIN EXIT IN HALL HA	Mon	2.101	PASS	
PULL STATION 2-102 IN CLASSROOM 73	Mon	2.102	PASS	
PULL STATION 2-103 IN CLASSROOM 72	Mon	2.103	PASS	
PULL STATION 2-104 IN CLASSROOM 75	Mon	2.104	PASS	
PULL STATION 2-105 IN CLASSROOM 60	Mon	2.105	PASS	
PULL STATION 2-106 EAST EXIT IN HALL HA BY GYM	Mon	2.106	PASS	
PULL STATION 2-107 EXIT IN GYM	Mon	2.107	PASS	
PULL STATION 2-108 NORTH EXIT BY GYM	Mon	2.108	PASS	
HOOD SYSTEM 2-109 IN KITCHEN	Mon	2.109	N/T	Not Tested.
PULL STATION 2-110 IN KITCHEN 12	Mon	2.110	PASS	
BPS 1 TROUBLE 2-111 IN A/V STORAGE 45 ROOM # 41	Mon	2.111	PASS	

REPORT OF INSPECTION

Additional Observations & Comments

1 Tested as installed.

2

3

4

5

6

7

8

9

10

Required Repairs and Compliance Issues That Will Result in a Yellow/Red Tag

1

2

3

4

5

REPORT OF INSPECTION

6

7

8

9

10



Flores Technical Services, Inc. dba F T S

NCTRCA D/M/WBE Certification # HMDB31312Y0707 ♦ HUB Certification #1752741251800
Security License B09038 ♦ Fire License ACR 1793 ♦ Electrical Contractors License #00052
13531 Floyd Circle Dallas, Texas 75243 (972) 792-7793 Office (972) 792-7149 Fax

FIRE ALARM INSPECTION REPORT

GISD - Sellers MS

10/25/2018



Flores Technical Services, Inc. dba F T S

NCTRCA D/M/WBE Certification # HMDB31312Y0707 ♦ HUB Certification #1752741251800
Security License B09038 ♦ Fire License ACR 1793 ♦ Electrical Contractors License #00052
13531 Floyd Circle Dallas, Texas 75243 (972) 792-7793 Office (972) 792-7149 Fax

FIRE ALARM INSPECTION AND TESTING FORM

Date: 10/25/2018 Time: 11:00

Client Name: GISD - Sellers MS Telephone: 972.494.8337

Contact Name: Keith Chapman Telephone: 972.487.4259

E-Mail: kachapma@garlandisd.net

Address: 1009 Mars Dr.

City/State/Zip: Garland, TX 75040-5852

Test Frequency: Annual Semi-Annual _____ Quarterly _____ Other _____

Date of Last Inspection: 8/28/2018 Date of Install: 8/28/2018

Date of Last System Service: unknown

Last date that any software/configuration was revised: Unknown

Fire Alarm Panel

Area Served/Location: Office

Fire Panel Manufacturer: SILENT KNIGHT Model: IFP-2000ECS

Upon arrival is system clear? Yes No _____

Existing tag color: White/Green Blue Yellow _____ Red _____

Notifications To Be Made Prior To Testing

Building Occupants: Yes _____ No Who Contacted _____ Time _____

Monitoring Company: GISD Security Who Contacted SCC Time 11:00

Phone Number: 972.487.4112 Account#: GISD

Line# 1: _____ Line# 2: _____

DACT Mfr/Model: SILENT KNIGHT ECS-125W Location: at FACP

MDI monitors Alarm, Supervisory, Trouble per AHJ.

Solenoids Removed By: n/a

Alarm Initiating Devices and Circuit Information

	Quantity	Circuit Style
Manual Pull Station:	18	SLC-6
HPM Pull Station:	0	
Ion Detector:	0	
Photoelectric Detector:	120	SLC-6
Duct Detector:	12	SLC-6
Heat Detector:	3	SLC-6
Waterflow Switch:	0	SLC-6
Tamper Switch:	0	SLC-6
Supervisory Switch:	0	
Control:	1	SLC-6
Other-Relays:	16	SLC-6
Other-Kitchen Hood:	1	SLC-6
Other-VESDA:	0	

Alarm Indicating Devices

	Quantity	Functional
Annunciators: (GCC)	1	Yes
Bells:	0	
Horns:	0	
Horn Strobes:	Multi	Yes
Strobes:	Multi	Yes
Speakers:	0	
Speaker Strobes:	0	
Are all circuits supervised? (Y/N)	Yes	

Auxiliary Functions

	Does Device Function Properly		
	Yes	No	N/A
Dampers:			X
Door Holders:			X
Exit Lights:			X
HVAC:	X		
Elevator Recall:			X
Mag Lock Drop Out:			X

Batteries

TESTED BY GISD

Battery Type: Sealed Lead Acid: _____ Lead Acid: _____ Quantity: _____

Date of Last Replacement: _____

Battery #1 Amp-Hour Rating: _____ Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating: _____ Volt/Amp-Hour Results: _____

On/Off Premises Monitoring

	Yes	No	N/A
Alarm Signal Received:	X		
Alarm Restoral Received:	X		
Supervisory Signal Received:	X		
Supervisory Restoral Received:	X		
Trouble Signal Received:	X		
Trouble Restoral Received:	X		

The following devices did not operate properly or did not meet current NFPA Standards:

Tested as installed. See additional sheets.

	Blue Tag	Yellow Tag	Red Tag
This system was tagged with a:	<u> X </u>	<u> </u>	<u> </u>

Solenoids Reconnected by: n/a

This system was restored to normal operation: Date 10/25/2018 Time 12:00 PM

This system was tested in accordance with all applicable NFPA Standards.

Date	<u> 10/25/2018 </u>		
Name of Inspector	<u> Martin DeAnda </u>	Signature	<u> On File </u>
License Number	<u> FAL-2081654 </u>		
Owner's Rep	<u> Keith Chapman </u>	Signature	<u> On File </u>

Signal Expander Panel Information TESTED BY GISD

Panel Name/Location: FACP

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: checked by GISD Quantity: 2

Battery #1 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Panel Name/Location: FCPS #1 Cust 103 Left L1M107 (Trigger) PS12/24-8 0 Spare

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: checked by GISD Quantity: 2

Battery #1 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Panel Name/Location: FCPS #2 Cust 103 Right L1M106 PS12/24-8 0 Spare

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: Checked by GISD Quantity: 2

Battery #1 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Panel Name/Location: FCPS #3 Cust. 59 L2M003 PS12/24-8 0 Spare

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: Checked by GISD Quantity: 2

Battery #1 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Signal Expander Panel Information

Panel Name/Location: FCPS #4 Cust. 99 L2M12 PS12/24-8 0 Spare

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: Checked by GISD Quantity: 2

Battery #1 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Panel Name/Location: FCPS #5 Cust. 99 L2M12 PS12/24-8 1 Spare

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: Checked by GISD Quantity: 2

Battery #1 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 12 Volt/Amp-Hour Results: _____

Panel Name/Location: DACT

Battery Type

Sealed Lead Acid: X Lead Acid: _____

Date of Last Replacement: Checked By GISD Quantity: 2

Battery #1 Amp-Hour Rating 7 Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating 7 Volt/Amp-Hour Results: _____

Panel Name/Location: _____

Battery Type

Sealed Lead Acid: _____ Lead Acid: _____

Date of Last Replacement: _____ Quantity: _____

Battery #1 Amp-Hour Rating _____ Volt/Amp-Hour Results: _____

Battery #2 Amp-Hour Rating _____ Volt/Amp-Hour Results: _____

Sellers

Address	Device Type	Description	Zone	Zone	Zone	Pass / Fail	Comments
LOOP #1							
D 1	Smoke(Photo)	ATTENDANCE OFFICE	10				
D 2	Smoke(Photo)	MAIN ENTRY	10				
D 3	Smoke(Photo)	T HALL	10				
D 4	Smoke(Photo)	K HALL	10				
D 5	Smoke(Photo)	K HALL	10				
D 6	Smoke(Photo)	K HALL	10				
D 7	Smoke(Photo)	K HALL	10				
D 8	Smoke(Photo)	CAFE ELECT RM	10				
D 9	Heat(Analog)	KITCHEN HEAT SENSOR	10				
D 10	Heat(Analog)	KITCHEN HEAT SENSOR	10				
D 11	Smoke(Photo)	CAFETERIA	10				
D 12	Smoke(Photo)	CAFETERIA	10				
D 13	Smoke(Photo)	CAFETERIA STAGE	10				
D 14	Smoke(Photo)	CAFETERIA EXIT	10				
D 15	Smoke(Photo)	CAFETERIA	10				
D 16	Smoke(Photo)	CAFETERIA	10				
D 17	Smoke(Photo)	CAFETERIA	10				
D 18	Smoke(Photo)	CAFETERIA DUCT DET	60	69			
D 19	Smoke(Photo)	CAFETERIA DUCT DET	60	70			
D 20	Smoke(Photo)	CAFETERIA	10				
D 21	Smoke(Photo)	T HALL CORR.	10				
D 22	Smoke(Photo)	T HALL CORR.	10				
D 23	Smoke(Photo)	C HALL CORR.	10				
D 24	Smoke(Photo)	C HALL CORR.	10				
D 25	Smoke(Photo)	C HALL CORR.	10				
D 26	Smoke(Photo)	S HALL CORR.	10				
D 27	Smoke(Photo)	S HALL CORR.	10				
D 28	Smoke(Photo)	S HALL CORR.	10				
D 29	Smoke(Photo)	S HALL CORR.	10				
D 30	Smoke(Photo)	BAND HALL CORRIDOR	10				
D 31	Smoke(Photo)	BAND HALL CORRIDOR	10				
D 32	Smoke(Photo)	RTU B4 BAND HALL	68	60			
D 33	Smoke(Photo)	BAND HALL PRACTICE	10				
D 34	Smoke(Photo)	GYM ELECT. RM.	10				
D 35	Smoke(Photo)	G HALL CORR.	10				
D 36	Smoke(Photo)	G HALL CORR.	10				
D 37	Smoke(Photo)	RTU B3 G HALL CORR.	67	60			
D 38	Smoke(Photo)	G HALL CORR.	10				
D 39	Smoke(Photo)	G HALL CORR.	10				
D 40	Smoke(Photo)	G HALL NORTH	10				
D 41	Smoke(Photo)	GYM.RTU-B8 DUCT DET.	72	60			
D 42	Smoke(Photo)	GYM.RTU-B7 DUCT DET.	71	60			
D 43	Smoke(Photo)	A HALL CORR.	10				
D 44	Smoke(Photo)	A HALL CORR.	10				
D 45	Smoke(Photo)	OLD GYM RTU DET	66	60			
D 46	Smoke(Photo)	OLD GYM RTU DET.	66	60			
D 47	Smoke(Photo)	C HALL CORR.	10				
D 48	Smoke(Photo)	C HALL CORR.	10				
D 49	Smoke(Photo)	ATTENDANCE OFFICE	10				
D 51	Smoke(Photo)	CHOIR ROOM	10				
D 52	Smoke(Photo)	SHOP CLASS	10				
D 53	Smoke(Photo)	SHOP CLASS	10				
D 54	Smoke(Photo)	SHOP CLASS	10				
D 55	Smoke(Photo)	SHOP CLASS	10				
D 56	Smoke(Photo)	GIRLS PE DRESS RM	10				
D 57	Smoke(Photo)	GIRLS PE DRESS RM	10				
D 58	Smoke(Photo)	BAND HALL	10				
D 59	Smoke(Photo)	BAND HALL	10				
D 61	Smoke(Photo)	BAND HALL	10				

Sellers

D 62	Smoke(Photo)	BOYS DRESSING ROOM	10			
D 64	Smoke(Photo)	AHU SHOP CLASS	60	73		
D 65	Smoke(Photo)	AHU SHOP CLASS	60	74		
D 66	Smoke(Photo)	BOYS PE DRESS RM	10			
D 67	Smoke(Photo)	BOYS PE DRESS RM	10			
D 68	Smoke(Photo)	LIBRARY	10			
D 69	Smoke(Photo)	LIBRARY	10			
D 70	Smoke(Photo)	T HALL FCPS	10			
D 71	Smoke(Photo)	T HALL ELECT. RM	10			
D 72	Smoke(Photo)	CHOIR STORAGE	10			
D 73	Smoke(Photo)	CLINIC	10			
D 75	Smoke(Photo)	GIRLS DRESSING RM.	10			
D 76	Smoke(Photo)	GIRLS DRESSING RM.	10			
D 77	Smoke(Photo)	KITCHEN ELEC RM	10			
D 80	Heat(Analog)	Hall G rm ac fr Gym	10			
D 81	Smoke(Photo)	IN WEIGHT ROOM	10			
D 82	Smoke(Photo)	IN WEIGHT ROOM	10			
D 83	Smoke(Photo)	IN WEIGHT ROOM	10			
D 84	Smoke(Photo)	IN WEIGHT ROOM	10			
D 85	Smoke(Photo)	BAND HALL	10			
D 86	Smoke(Photo)	BOYS DRESSING	10			
M 2	Monitor Pull Station	HALL EXIT	10			
M 3	Monitor Pull Station		10			
M 4	Monitor Monitor		10			
M 5	Relay		69			
M 6	Monitor Trouble Mon	HALL FCPS	99			
M 7	Control	HALL FCPS	10	80		
M 9	Monitor Pull Station	HALL EXIT	10			
M 10	Monitor Trouble Mon	HALL FCPS.	99			
M 11	Relay		73			
M 12	Relay		74			
M 13	Monitor Pull Station	HALL EXIT	10			
M 14	Relay		68			
M 15	Monitor Pull Station	HALL EXIT	10			
M 16	Monitor Pull Station		10			
M 17	Monitor Pull Station		10			
M 18	Monitor Pull Station		10			
M 19	Monitor Trouble Mon		99			
M 20	Relay		67			
M 22	Relay		72			
M 23	Relay		71			
M 24	Monitor Pull Station		10			
M 25	Monitor Pull Station		10			
M 26	Monitor Pull Station		10			
M 27	Relay		10			
M 28	Relay		66			
M 29	Relay		66			
M 31	Monitor Pull Station		10			
M 32	Monitor Pull Station		10			
M 33	Relay		70			
M 34	Monitor Pull Station		10			
M 36	Monitor Monitor		10			
LOOP #2						
D 2	Smoke(Photo)	MAIN ENTRY LOBBY	10			
D 3	Smoke(Photo)	B HALL CORR.	10			
D 4	Smoke(Photo)	B HALL CORR.	10			
D 5	Smoke(Photo)	COMPUTER RM OFFICE	10			
D 6	Smoke(Photo)	B HALL CORR.	10			
D 7	Smoke(Photo)	B HALL CORR.	10			
D 8	Smoke(Photo)	B HALL EXIT	10			
D 9	Smoke(Photo)	B HALL CORR.	10			

Sellers

D 10	Smoke(Photo)	B HALL CORR.	10			
D 11	Smoke(Photo)	A HALL CORR.	10			
D 12	Smoke(Photo)	A HALL JAN, CLOSET	10			
D 13	Smoke(Photo)	A HALL CORR.	10			
D 14	Smoke(Photo)	A HALL CORR.	10			
D 15	Smoke(Photo)	THEATRE OFFICE	10			
D 16	Smoke(Photo)	D HALL CORR.	10			
D 17	Smoke(Photo)	D HALL ELECT RM.	10			
D 18	Smoke(Photo)	D HALL CORR.	10			
D 19	Smoke(Photo)	D HALL CORR.	10			
D 20	Smoke(Photo)	D HALL CORR.	10			
D 21	Smoke(Photo)	D HALL CORR.	10			
D 22	Smoke(Photo)	D HALL CORR.	10			
D 23	Smoke(Photo)	D-Hall Fire Door	10			
D 24	Smoke(Photo)	D-Hall Fire Door	10			
D 25	Smoke(Photo)	D-Hall CORR.	10			
D 26	Smoke(Photo)	F Hall	10			
D 27	Smoke(Photo)	F Hall	10			
D 28	Smoke(Photo)	RTU A3 Rm 119	60	63		
D 29	Smoke(Photo)	F Hall CORR	10			
D 30	Smoke(Photo)	F Hall CORR	10			
D 31	Smoke(Photo)	RTU A4 Rm 121	60	84		
D 32	Smoke(Photo)	F Hall Cor	10			
D 33	Smoke(Photo)	F Hall Cor	10			
D 34	Smoke(Photo)	E Hall CORR	10			
D 35	Smoke(Photo)	E Hall Elect Rm	10			
D 36	Smoke(Photo)	E Hall Fire Door	10			
D 37	Smoke(Photo)	E Hall Fire Door	10			
D 38	Smoke(Photo)	E HALL CORR.	10			
D 39	Smoke(Photo)	E. HALL CORR.	10			
D 40	Smoke(Photo)	E. HALL CORR.	10			
D 41	Smoke(Photo)	E. HALL CORR.	10			
D 42	Smoke(Photo)	E. HALL CORR.	10			
D 43	Smoke(Photo)	E. HALL CORR.	10			
D 44	Smoke(Photo)	E HALL CORR.	10			
D 45	Smoke(Photo)	A HALL CORR.	10			
D 46	Smoke(Photo)	A HALL JAN. RM	10			
D 47	Smoke(Photo)	A HALL CORR.	10			
D 48	Smoke(Photo)	SCIENCE LAB STORAGE	10			
D 49	Smoke(Photo)	SCIENCE LAB RM. 25	10			
D 51	Smoke(Photo)	SCIENCE LAB RM. 24	10			
D 52	Smoke(Photo)	SCIENCE LAB RM. 24	10			
D 53	Smoke(Photo)	Rm 121 SCIENCE LAB	10			
D 54	Smoke(Photo)	Rm 119 SCIENCE LAB	10			
D 55	Smoke(Photo)	MDF Rm in Rm 26	10			
D 58	Smoke(Photo)	CUSTODIANS RM.59	10			
D 70	Smoke(Photo)	MUSIC RM 20	10			
M 2	Monitor Pull Station	HALL EXIT	10			
M 3	Monitor Trouble Mon		99			
M 4	Monitor Pull Station		10			
M 6	Monitor Pull Station	HALL EXIT	10			
M 7	Relay		63			
M 8	Relay		64			
M 9	Monitor Pull Station	HALL EXIT	10			
M 10	Monitor Trouble Mon	HALL FCPS	99			
M 11	Relay		10			
M 12	Monitor Trouble Mon	HALL FCPS	99			
M 15	Relay		10	80		
M 16	Relay		98	99		
M 17	Monitor Non Fire		98			

REPORT OF INSPECTION

Client Name: Sellers MS 10/25/18

Area/Zone/Phase: _____

Additional Comments

1 Tested as installed.

2 All Batteries Tested By GISD

3 Need New Point List.

4 _____

5 _____

6 _____

7 _____

8 _____

9 _____

10 _____

11 _____

12 _____

13 _____

14 _____

15 _____



Flores Technical Services, Inc. dba F T S

NCTRCA D/M/WBE Certification # HMDB31312Y0707 ♦ HUB Certification #1752741251800
Security License B09038 ♦ Fire License ACR 1793 ♦ Electrical Contractors License #00052
13531 Floyd Circle Dallas, Texas 75243 (972) 792-7793 Office (972) 792-7149 Fax

FIRE ALARM INSPECTION REPORT

GISD - Rowlett HS

10/29/2018



Flores Technical Services, Inc. dba F T S

NCTRCA D/M/WBE Certification # HMDB31312Y0707 ♦ HUB Certification #1752741251800
Security License B09038 ♦ Fire License ACR 1793 ♦ Electrical Contractors License #00052
13531 Floyd Circle Dallas, Texas 75243 (972) 792-7793 Office (972) 792-7149 Fax

FIRE ALARM INSPECTION AND TESTING FORM

Date: 10/29/2018 Time: 6:00

Client Name: GISD - Rowlett HS Telephone: 972.463.1712

Contact Name: Keith Chapman Telephone: 972.487.4259
E-Mail: kachapma@qartandisd.net

Address: 4700 Kirby Rd.

City/State/Zip: Rowlett, TX 75088-5191

Test Frequency: Annual Semi-Annual _____ Quarterly _____ Other _____

Date of Last Inspection: 7/15/2016 Date of Install: 6/4/2009

Date of Last System Service: 5/14/2013

Last date that any software/configuration was revised: Unknown

Fire Alarm Panel

Area Served/Location: AP Office

Fire Panel Manufacturer: Harrington Model: HS3200 (Three Panels)

Upon arrival is system clear? Yes No _____

Existing tag color: White/Green _____ Blue Yellow _____ Red _____

Notifications To Be Made Prior To Testing

Building Occupants: Yes _____ No Who Contacted _____ Time _____

Monitoring Company: GISD Security Who Contacted _____ Time 6:00 PM

Phone Number: 972.487.4112 Account#: GISD

Line# 1: _____ Line# 2: _____

DACT Mfr/Model: _____ Location: MDI monitors Alarm, Supervisory, Trouble per AHJ.

Solenoids Removed By: n/a

Alarm Initiating Devices and Circuit Information

	Quantity	Circuit Style
Manual Pull Station:	39	SLC-6
HPM Pull Station:	0	
Ion Detector:	0	
Photoelectric Detector:	259	SLC-6
Duct Detector:	32	SLC-6
Heat Detector:	46	SLC-6
Waterflow Switch:	9	SLC-6
Tamper Switch:	9	SLC-6
Supervisory Switch:	0	
Control:	0	
Other-Relays:	5	SLC-6
Other-Kitchen Hood:	2	SLC-6
Other-Beam Det:	3	SLC-6

Alarm Indicating Devices

	Quantity	Functional
Annunciators: (GCC)	3	Yes
Bells:	0	
Horns:	0	
Horn Strobes:	Multi	Yes
Strobes:	Multi	Yes
Speakers:	0	
Speaker Strobes:	0	
Are all circuits supervised? (Y/N)	Yes	

Auxiliary Functions

	Does Device Function Properly		
	Yes	No	N/A
Dampers:			X
Door Holders:	X		
Exit Lights:			X
HVAC:	X		
Elevator Recall:		X	
Mag Lock Drop Out:	X		

Batteries

Batteries tested by GISD

Battery Type: Sealed Lead Acid: _____ Lead Acid: _____ Quantity: _____
 Date of Last Replacement: _____
 Battery #1 Amp-Hour Rating: _____ Volt/Amp-Hour Results: _____
 Battery #2 Amp-Hour Rating: _____ Volt/Amp-Hour Results: _____

On/Off Premises Monitoring

	Yes	No	N/A
Alarm Signal Received:	X		
Alarm Restoral Received:	X		
Supervisory Signal Received:	X		
Supervisory Restoral Received:	X		
Trouble Signal Received:	X		
Trouble Restoral Received:	X		

The following devices did not operate properly or did not meet current NFPA Standards:

Tested as installed. See additional sheets.

	Blue Tag	Yellow Tag	Red Tag
This system was tagged with a:	<u> X </u>	<u> </u>	<u> X </u>

Solenoids Reconnected by: n/a

This system was restored to normal operation: Date 10/29/2018 Time 1:30 AM

This system was tested in accordance with all applicable NFPA Standards.

Date	<u>10/29/2018</u>		
Name of Inspector	<u>Martin DeAnda</u>	Signature	<u>On File</u>
License Number	<u>FAL-2081654</u>		
Owner's Rep	<u>Keith Chapman</u>	Signature	<u>On File</u>

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
1ST FLOOR SMOKE DETECTOR 1-1 N/W CAFE ENTRY DOORS	Photo	1.1	Pass	
1ST FLOOR SMOKE DETECTOR 1-2 ELEVATOR LOBBY	Photo	1.2	Pass	
1ST FLOOR SMOKE DETECTOR 1-3 N/W CAFE ENTRY DOORS	Photo	1.3	Pass	
1ST FLOOR SMOKE DETECTOR 1-4 HALL BY CLASS 1220	Photo	1.4	Pass	
1ST FLOOR SMOKE DETECTOR 1-5 HALL BY CLASS 1154	Photo	1.5	Pass	
1ST FLOOR SMOKE DETECTOR 1-6 HALL BY CLASS 1152	Photo	1.6	Pass	
1ST FLOOR HEAT DETECTOR 1-7 KITCHEN IN CLASS 1154	Thrml	1.7	Pass	
1ST FLOOR SMOKE DETECTOR 1-8 HALL BY CLASS 1150	Photo	1.8	Pass	
1ST FLOOR SMOKE DETECTOR 1-9 BOYS RR 1137	Photo	1.9	Pass	
1ST FLOOR SMOKE DETECTOR 1-10 GIRLS RR 1138	Photo	1.10	Pass	
1ST FLOOR SMOKE DETECTOR 1-12 HALL BY STAIRS # 2	Photo	1.12	Pass	
1ST FLOOR SMOKE DETECTOR 1-13 HALL BY CLASS 1134	Photo	1.13	Pass	
1ST FLOOR SMOKE DETECTOR 1-14 HALL BY EAST COMP RM	Photo	1.14	Pass	
1ST FLOOR SMOKE DETECTOR 1-15 HALL BY CLASS 1111	Photo	1.15	Pass	
1ST FLOOR SMOKE DETECTOR 1-16 HALL BY CLASS 1109	Photo	1.16	Pass	
1ST FLOOR SMOKE DETECTOR 1-17 HALL BY HOME EC 1105	Photo	1.17	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
1ST FLOOR HEAT DETECTOR 1-18 HOME ECON RM 1105	Thrml	1.18	Pass	
1ST FLOOR HEAT DETECTOR 1-19 HOME ECON RM 1103	Thrml	1.19	Pass	
1ST FLOOR SMOKE DETECTOR 1-20 HALL BY HOME EC 1103	Photo	1.20	Pass	
1ST FLOOR SMOKE DETECTOR 1-21 BOYS RR BY ART 1100	Photo	1.21	Pass	
1ST FLOOR SMOKE DETECTOR 1-22 GIRLS RR BY ART 1101	Photo	1.22	Pass	
1ST FLOOR HEAT DETECTOR 1-23 ART RM 1102 KILN RM	Thrml	1.23	Pass	
1ST FLOOR SMOKE DETECTOR 1-24 RR IN CLASS RM 1110C	Photo	1.24	Pass	
1ST FLOOR SMOKE DETECTOR 1-25 HALL BY SCIENCE 1131	Photo	1.25	Pass	
1ST FLOOR SMOKE DETECTOR 1-26 HALL BY CLASS 1133	Photo	1.26	Pass	
1ST FLOOR SMOKE DETECTOR 1-27 HALL BY BUSINES 1111	Photo	1.27	Pass	
1ST FLOOR SMOKE DETECTOR 1-28 CLASS ROOM 1140	Photo	1.28	Pass	
1ST FLOOR SMOKE DETECTOR 1-29 HALL BY CLASS 1140	Photo	1.29	Pass	
1ST FLOOR SMOKE DETECTOR 1-30 HALL BY COMP RM 1142	Photo	1.30	Pass	
1ST FLOOR SMOKE DETECTOR 1-31 COMPUTER RM 1142	Photo	1.31	Pass	
1ST FLOOR SMOKE DETECTOR 1-32 COMPUTER RM 1144	Photo	1.32	Pass	
1ST FLOOR SMOKE DETECTOR 1-33 GIRLS RR 1143	Photo	1.33	Pass	
1ST FLOOR SMOKE DETECTOR 1-34 ELEC RM E 11.1	Photo	1.34	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
1ST FLOOR SMOKE DETECTOR 1-35 PREP RM SCIENCE 1206	Photo	1.35	Pass	
1ST FLOOR SMOKE DETECTOR 1-36 PREP RM SCIENCE 1204	Photo	1.36	Pass	
1ST FLOOR SMOKE DETECTOR 1-37 PREP RM SCIENCE 1202	Photo	1.37	Pass	
1ST FLOOR SMOKE DETECTOR 1-38 BOYS RR 1145	Photo	1.38	Pass	
1ST FLOOR SMOKE DETECTOR 1-39 HALL BY COMP RM 1144	Photo	1.39	Pass	
1ST FLOOR SMOKE DETECTOR 1-40 E STAIR WAY # 3	Photo	1.40	Pass	
1ST FLOOR SMOKE DETECTOR 1-41 HALL BY CLASS 1212	Photo	1.41	Pass	
1ST FLOOR SMOKE DETECTOR 1-42 GIRL RR 1211	Photo	1.42	Pass	
1ST FLOOR SMOKE DETECTOR 1-43 BOYS RR 1210	Photo	1.43	Pass	
1ST FLOOR SMOKE DETECTOR 1-44 HALL BY OFFICES 1207	Photo	1.44	Pass	
1ST FLOOR SMOKE DETECTOR 1-45 HALL BY SCIENCE 1205	Photo	1.45	Pass	
1ST FLOOR SMOKE DETECTOR 1-46 HALL BY SCIENCE 1203	Photo	1.46	Pass	
1ST FLOOR SMOKE DETECTOR 1-47 HALL BY SCIENCE 1201	Photo	1.47	Pass	
1ST FLOOR SMOKE DETECTOR 1-48 PREP RM SCIENCE 1203	Photo	1.48	Pass	
1ST FLOOR SMOKE DETECTOR 1-49 PREP RM SCIENCE 1205	Photo	1.49	Pass	
1ST FLOOR SMOKE DETECTOR 1-50 HALL IN OFFICE 1207	Photo	1.50	Pass	
1ST FLOOR HEAT DETECTOR 1-51	ThrmI	1.51	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
BRK RM IN OFFICE1207				

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
1ST FLOOR SMOKE DETECTOR 1-52 HALL IN OFFICE 1207	Photo	1.52	Pass	
1ST FLOOR SMOKE DETECTOR 1-53 HALL BY CLASS 1214	Photo	1.53	Pass	
1ST FLOOR SMOKE DETECTOR 1-54 HALL BY CLASS 1215	Photo	1.54	Pass	
1ST FLOOR SMOKE DETECTOR 1-55 HALL BY CLASS 1236	Photo	1.55	Pass	
1ST FLOOR SMOKE DETECTOR 1-56 HALL BY CLASS 1232	Photo	1.56	Pass	
1ST FLOOR SMOKE DETECTOR 1-57 HALL BY SCIENCE 1231	Photo	1.57	Pass	
1ST FLOOR SMOKE DETECTOR 1-58 HALL BY SCIENCE 1230	Photo	1.58	Pass	
1ST FLOOR SMOKE DETECTOR 1-59 STAIR # 4	Photo	1.59	Pass	
1ST FLOOR SMOKE DETECTOR 1-60 ELEC RM E12.0	Photo	1.60	Pass	
1ST FLOOR SMOKE DETECTOR 1-61 HALL BY CLASS 1239	Photo	1.61	Pass	
1ST FLOOR SMOKE DETECTOR 1-62 HALL BY CLASS 1241	Photo	1.62	Pass	
1ST FLOOR SMOKE DETECTOR 1-63 HALL BY CLASS 1226	Photo	1.63	Pass	
1ST FLOOR SMOKE DETECTOR 1-64 HALL BY CLASS 1226	Photo	1.64	Pass	
1ST FLOOR SMOKE DETECTOR 1-65 HALL BY CLASS 1224	Photo	1.65	Pass	
1ST FLOOR SMOKE DETECTOR 1-66 GIRLS RR 1243	Photo	1.66	Pass	
1ST FLOOR SMOKE DETECTOR 1-67 BOYS RR 1245	Photo	1.67	Pass	
1ST FLOOR SMOKE DETECTOR 1-68	Photo	1.68	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
IN HALL BY STAIRS 5				

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
1ST FLOOR SMOKE DETECTOR 1-69 STAIRS # 5 BY CLINIC	Photo	1.69	Pass	
1ST FLOOR SMOKE DETECTOR 1-70 HALL BY CLINIC 1301	Photo	1.70	Pass	
1ST FLOOR SMOKE DETECTOR 1-71 HALL BY OFFICE 1302	Photo	1.71	Pass	
1ST FLOOR SMOKE DETECTOR 1-72 HALL BY OFFICE 1302	Photo	1.72	Pass	
1ST FLOOR SMOKE DETECTOR 1-73 FRONT RECEPTION 1302	Photo	1.73	Pass	
1ST FLOOR SMOKE DETECTOR 1-74 OFFICE REST RM 1307	Photo	1.74	Pass	
1ST FLOOR SMOKE DETECTOR 1-75 OFFICE REST RM 1308	Photo	1.75	Pass	
1ST FLOOR SMOKE DETECTOR 1-76 OFFICE HALL BY 1302B	Photo	1.76	Pass	
1ST FLOOR SMOKE DETECTOR 1-77 CLINIC REST RM 1301H	Photo	1.77	Pass	
1ST FLOOR SMOKE DETECTOR 1-78 CLINIC REST RM 1301J	Photo	1.78	Pass	
1ST FLOOR SMOKE DETECTOR 1-79 CLINIC SLEEPING AREA	Photo	1.79	Pass	
1ST FLOOR HEAT DETECTOR 1-80 OFFICE WORK RM1306	ThrmI	1.80	Pass	
1ST FLOOR SMOKE DETECTOR 1-81 OFFICE HALL BY 1306	Photo	1.81	Pass	
1ST FLOOR SMOKE DETECTOR 1-82 HALL IN FRONT OFFICE	Photo	1.82	Pass	
1ST FLOOR SMOKE DETECTOR 1-83 HALL BY CLASS 1222	Photo	1.83	Pass	
1ST FLOOR SMOKE DETECTOR 1-84 ELEC RM E 15.0	Photo	1.84	Pass	
1ST FLOOR SMOKE DETECTOR 1-85	Photo	1.85	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
OFFICE HALL BY 1302D 1ST FLOOR SMOKE DETECTOR 1-86 OFFICE HALL BY 1303T	Photo	1.86	Pass	
1ST FLOOR SMOKE DETECTOR 1-87 OFFICE IDF RM 1304F	Photo	1.87	Pass	
1ST FLOOR SMOKE DETECTOR 1-88 ATTENDANCE RM 1400	Photo	1.88	Pass	
1ST FLOOR SMOKE DETECTOR 1-89 IN CLASS ROOM 1106	Photo	1.89	Pass	
1ST FLOOR PULL STATION 1-101 EAST EXIT BY CAFE	Mon	1.101	Pass	
1ST FLOOR PULL STATION 1-102 EAST EXIT E REST RMS	Mon	1.102	Pass	
1ST FLOOR PULL STATION 1-103 EXIT BY SCIENCE 1201	Mon	1.103	Pass	
1ST FLOOR PULL STATION 1-104 EXIT BY SCIENCE 1230	Mon	1.104	Pass	
1ST FLOOR PULL STATION 1-105 STAIR EXIT BY CLINIC	Mon	1.105	Pass	
1ST FLOOR PULL STATION 1-106 EXIT BY CLINIC	Mon	1.106	Pass	
1ST FLOOR PULL STATION 1-107 MAIN FRONT ENTRANCE	Mon	1.107	Pass	
1ST FLOOR BPS PNL # 1 1-108 ELEC ROOM # E 12.0	Mon	1.108	Pass	
1ST FLOOR BPS PNL # 2 1-109 ELEC ROOM # E 15.0	Mon	1.109	Pass	
1ST FLOOR BPS PNL # 3 1-110 ELEC ROOM # E 11.1	Mon	1.110	Pass	
1ST FLOOR BPS PNL # 10 1-111 ELEC ROOM # E 11.1	Mon	1.111	Pass	
1ST FLOOR PULL STATION 1-112 IN STAIRS # 4	Mon	1.112	Pass	
1ST FLOOR	Photo	2.1	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
SMOKE DETECTOR 2-1 ABOVE FIRE PANEL				
1ST FLOOR HEAT DETECTOR 2-2 OFFICE WORK RM 1303B	Thrml	2.2	Pass	
1ST FLOOR SMOKE DETECTOR 2-3 RECEPTION AREA 1303	Photo	2.3	Pass	
1ST FLOOR SMOKE DETECTOR 2-4 CAFE HALL BY SERVING	Photo	2.4	Pass	
1ST FLOOR SMOKE DETECTOR 2-5 CAFE HALL BY SERVING	Photo	2.5	Pass	
1ST FLOOR SMOKE DETECTOR 2-6 CAFE HALL DISHWASH	Photo	2.6	Pass	
1ST FLOOR SMOKE DETECTOR 2-7 CAFE HALL BY SERVING	Photo	2.7	Pass	
1ST FLOOR SMOKE DETECTOR 2-8 CAFE HALL BY SERVING	Photo	2.8	Pass	
1ST FLOOR SMOKE DETECTOR 2-9 EAST CAFE ENTRY	Photo	2.9	Pass	
1ST FLOOR SMOKE DETECTOR 2-10 EAST CAFE ENTRY	Photo	2.10	Pass	
1ST FLOOR SMOKE DETECTOR 2-11 EAST HALL BY GYM	Photo	2.11	Pass	
1ST FLOOR SMOKE DETECTOR 2-12 EAST HALL BY GYM	Photo	2.12	Pass	
1ST FLOOR SMOKE DETECTOR 2-13 EAST HALL BY GYM	Photo	2.13	Pass	
1ST FLOOR SMOKE DETECTOR 2-14 EAST HALL BY GYM	Photo	2.14	Pass	
1ST FLOOR SMOKE DETECTOR 2-15 EAST EXIT BY GYM	Photo	2.15	Pass	
1ST FLOOR DUCT DETECTOR 2-16 GYM N/W AHU	Photo	2.16	Pass	
1ST FLOOR DUCT DETECTOR 2-17 GYM S/W AHU	Photo	2.17	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
1ST FLOOR DUCT DETECTOR 2-18 GYM CENTER SOUTH AHU	Photo	2.18	Pass	
1ST FLOOR DUCT DETECTOR 2-19 GYM CENTER NORTH AHU	Photo	2.19	Pass	
1ST FLOOR DUCT DETECTOR 2-20 GYM EAST AHU	Photo	2.20	Pass	
1ST FLOOR DUCT DETECTOR 2-21 LOCKER RM EAST AHU	Photo	2.21	Pass	
1ST FLOOR SMOKE DETECTOR 2-22 LOCKER RM HALLWAY	Photo	2.22	Pass	
1ST FLOOR HEAT DETECTOR 2-23 BOYS PE SHOWER 1620B	Thrml	2.23	Pass	
1ST FLOOR SMOKE DETECTOR 2-24 BOYS JV LKR RM 1623	Photo	2.24	Pass	
1ST FLOOR SMOKE DETECTOR 2-25 HALL BY ELECRM E16.0	Photo	2.25	Pass	
1ST FLOOR SMOKE DETECTOR 2-26 LOCKER ELEC RM E16.0	Photo	2.26	Pass	
1ST FLOOR DUCT DETECTOR 2-27 AHUIN HALL BY RM1604	Photo	2.27	Pass	
1ST FLOOR SMOKE DETECTOR 2-25 HALL BY RM 1604	Photo	2.28	Pass	
1ST FLOOR HEAT DETECTOR 2-29 IN LAUNDRY RM 1604	Thrml	2.29	Pass	
1ST FLOOR HEAT DETECTOR 2-30 BOYS LOCKER RR 1623B	Thrml	2.30	Pass	
1ST FLOOR HEAT DETECTOR 2-31 BOYS COACH RR 1622B	Thrml	2.31	Pass	
1ST FLOOR HEAT DETECTOR 2-32 BOYS LOCKER RR 1621B	Thrml	2.32	Pass	
1ST FLOOR HEAT DETECTOR 2-33 GIRLS LOCKER RR1614B	Thrml	2.33	Pass	
1ST FLOOR HEAT DETECTOR 2-34	Thrml	2.34	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
GIRLS COACH RR 1612B 1ST FLOOR HEAT DETECTOR 2-35 GIRLS LOCKER RR1610B	Thrml	2.35	Pass	
1ST FLOOR SMOKE DETECTOR 2-36 HALL BY LKR RM 1610	Photo	2.36	Pass	
1ST FLOOR DUCT DETECTOR 2-37 AHU INHALL BY RM1610	Photo	2.37	Pass	
1ST FLOOR SMOKE DETECTOR 2-38 HALL BY LKR RM 1610	Photo	2.38	Pass	
1ST FLOOR SMOKE DETECTOR 2-36 HALL BY RM 1612	Photo	2.39	Pass	
1ST FLOOR HEAT DETECTOR 2-40 GIRLS LOCKER RR1602	Thrml	2.40	Pass	
1ST FLOOR SMOKE DETECTOR 2-41 HALL BY LKR RM 1602	Photo	2.41	Pass	
1ST FLOOR DUCT DETECTOR 2-42 AHU BY LKR RM 1602	Photo	2.42	Pass	
1ST FLOOR SMOKE DETECTOR 2-43 LOCKER RM SOUTH EXIT	Photo	2.43	Pass	
1ST FLOOR SMOKE DETECTOR 2-44 HALL BY DANCE RM1511	Photo	2.44	Pass	
1ST FLOOR SMOKE DETECTOR 2-45 HALL BY BOYS RR1509	Photo	2.45	Pass	
1ST FLOOR SMOKE DETECTOR 2-46 PRIVATE RR 1510	Photo	2.46	Pass	
1ST FLOOR SMOKE DETECTOR 2-47 BOYS RR BY GYM 1509	Photo	2.47	Pass	
1ST FLOOR SMOKE DETECTOR 2-48 GIRLS RR BY GYM 1507	Photo	2.48	Pass	
1ST FLOOR DUCT DETECTOR 2-49 HALL BY GIRLS RR1507	Photo	2.49	Pass	
1ST FLOOR SMOKE DETECTOR 2-50 HALL BY GIRLS RR1507	Photo	2.50	Pass	
1ST FLOOR	Photo	2.51	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
DUCT DETECTOR 2-51 HALL BY GIRLS RR1507				
1ST FLOOR HEAT DETECTOR 2-52 CAFE E SERVING AREA	Thrml	2.52	Pass	
1ST FLOOR HEAT DETECTOR 2-53 CAFE KITCHEN AREA	Thrml	2.53	Pass	
1ST FLOOR HEAT DETECTOR 2-54 CAFE E SERVING AREA	Thrml	2.54	Pass	
1ST FLOOR HEAT DETECTOR 2-55 CAFE KITCHEN AREA	Thrml	2.55	Pass	
1ST FLOOR SMOKE DETECTOR 2-56 CAFE KITCHEN REST RM	Photo	2.56	Pass	
1ST FLOOR HEAT DETECTOR 2-57 CAFE FOOD PREP AREA	Thrml	2.57	Pass	
1ST FLOOR HEAT DETECTOR 2-58 CAFE FOOD PREP AREA	Thrml	2.58	Pass	
1ST FLOOR HEAT DETECTOR 2-59 CAFE W SERVING AREA	Thrml	2.59	Pass	
1ST FLOOR HEAT DETECTOR 2-60 CAFE SOUTH MECH RM	Thrml	2.60	Pass	
1ST FLOOR HEAT DETECTOR 2-61 CAFE SOUTH MECH RM	Thrml	2.61	Pass	
1ST FLOOR HEAT DETECTOR 2-62 CAFE SOUTH MECH RM	Thrml	2.62	Pass	
1ST FLOOR HEAT DETECTOR 2-63 CAFE SOUTH ELEC RM	Thrml	2.63	Pass	
1ST FLOOR DUCT DETECTOR 2-64 BY GIRLS RR 1405	Photo	2.64	Pass	
1ST FLOOR SMOKE DETECTOR 2-65 BY GIRLS RR BY STAGE	Photo	2.65	Pass	
1ST FLOOR SMOKE DETECTOR 2-66 HALL BY THEATRE ARTS	Photo	2.66	Pass	
1ST FLOOR DUCT DETECTOR 2-67 BAND ROOM STORAGE	Photo	2.67	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
1ST FLOOR SMOKE DETECTOR 2-68 ELEC RM BY BAND ROOM	Photo	2.68	Pass	
1ST FLOOR SMOKE DETECTOR 2-69 REST RM BY BAND ROOM	Photo	2.69	Pass	
1ST FLOOR SMOKE DETECTOR 2-70 REST RM BY BAND ROOM	Photo	2.70	Pass	
1ST FLOOR SMOKE DETECTOR 2-71 DRESSRM BY BAND ROOM	Photo	2.71	Pass	
1ST FLOOR SMOKE DETECTOR 2-72 BAND ROOM ENTRY	Photo	2.72	Pass	
1ST FLOOR SMOKE DETECTOR 2-73 HALL IN ENSEMBLE RM	Photo	2.73	Pass	
1ST FLOOR DUCT DETECTOR 2-74 CHOIR ROOM	Photo	2.74	Pass	
1ST FLOOR SMOKE DETECTOR 2-75 CHOIR ROOM ENTRY	Photo	2.75	Pass	
1ST FLOOR SMOKE DETECTOR 2-76 HALL BY CHOIR ROOM	Photo	2.76	Pass	
1ST FLOOR SMOKE DETECTOR 2-77 HALL BY BAND RROOM	Photo	2.77	Pass	
1ST FLOOR SMOKE DETECTOR 2-78 HALL BY THEATRE ARTS	Photo	2.78	Pass	
1ST FLOOR SMOKE DETECTOR 2-79 ELEC RM THEATRE ARTS	Photo	2.79	Pass	
1ST FLOOR SMOKE DETECTOR 2-80 S/E STAGE AREA	Photo	2.80	Pass	
1ST FLOOR SMOKE DETECTOR 2-82 GIRLS RR BY STAGE	Photo	2.82	Pass	
1ST FLOOR SMOKE DETECTOR 2-83 BOYS RR BY STAGE	Photo	2.83	Pass	
1ST FLOOR SMOKE DETECTOR 2-84 BY BOYS RR BY STAGE	Photo	2.84	Pass	
1ST FLOOR SMOKE DETECTOR 2-85	Photo	2.85	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
HALL BY AUDITORIUM				
1ST FLOOR DUCT DETECTOR 2-86 BY BOYS RR 1404	Photo	2.86	Pass	
1ST FLOOR DUCT DETECTOR 2-87 BY BUILDING ENG 1402	Photo	2.87	Pass	
1ST FLOOR DUCT DETECTOR 2-88 IN SERVING RM 1502A	Photo	2.88	Pass	
1ST FLOOR DUCT DETECTOR 2-89 IN PREP AREA 1502	Photo	2.89	Pass	
1ST FLOOR DUCT DETECTOR 2-90 IN SERVING RM 1504E	Photo	2.90	Pass	
1ST FLOOR DUCT DETECTOR 2-91 IN ROOM 1503	Photo	2.91	Pass	
1ST FLOOR DUCT DETECTOR 2-92 IN SERVING RM 4	Photo	2.92	Pass	
1ST FLOOR SMOKE DETECTOR 2-93 DRESSRM BY BAND ROOM	Photo	2.93	Pass	
1ST FLOOR HEAT DETECTOR 2-94 IN ROOM 1508	Thrml	2.94	Pass	
1ST FLOOR HEAT DETECTOR 2-95 IN ROOM 1611	Thrml	2.95	Pass	
1ST FLOOR HEAT DETECTOR 2-96 IN ROOM 1605	Thrml	2.96	Pass	
1ST FLOOR PULL STATION 2-101 EAST EXIT BY GYM	Mon	2.101	Pass	
1ST FLOOR PULL STATION 2-102 S/E EXIT IN GYM	Mon	2.102	Pass	
1ST FLOOR PULL STATION 2-103 S/E EXIT BY GYM	Mon	2.103	Pass	
1ST FLOOR PULL STATION 2-104 S/E LOCKER RM EXIT	Mon	2.104	Pass	
1ST FLOOR PULL STATION 2-105 S/W LOCKER RM EXIT	Mon	2.105	Pass	
1ST FLOOR	Mon	2.106	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
PULL STATION 2-106 SOUTH EXIT BY GYM				
1ST FLOOR PULL STATION 2-107 SOUTH EXIT BY GYM	Mon	2.107	Pass	
1ST FLOOR KITCHEN HOOD 2-109 SOUTH HOOD	Mon	2.109	N/T	NOT TESTED
1ST FLOOR PULL STATION 2-111 EAST EXIT BY STAGE	Mon	2.111	Pass	
1ST FLOOR WATERFLOW 2-112 RISER # 1	Mon	2.112	N/T	YELLOW TAG
1ST FLOOR TAMPER VALVE 2-113 RISER # 1	Mon	2.113	Pass	
1ST FLOOR WATERFLOW 2-114 RISER # 2	Mon	2.114	N/T	YELLOW TAG
1ST FLOOR TAMPER VALVE 2-115 RISER # 2	Mon	2.115	Pass	
1ST FLOOR WATERFLOW 2-116 RISER # 3	Mon	2.116	N/T	YELLOW TAG
1ST FLOOR TAMPER VALVE 2-117 RISER # 3	Mon	2.117	Pass	
1ST FLOOR WATERFLOW 2-118 RISER # 4	Mon	2.118	N/T	YELLOW TAG
1ST FLOOR TAMPER VALVE 2-119 RISER # 4	Mon	2.119	Pass	
1ST FLOOR WATERFLOW 2-120 RISER # 5	Mon	2.120	N/T	YELLOW TAG
1ST FLOOR TAMPER VALVE 2-121 RISER # 5	Mon	2.121	Pass	
1ST FLOOR WATERFLOW 2-122 RISER # 6 STAGE	Mon	2.122	N/T	YELLOW TAG
1ST FLOOR TAMPER VALVE 2-123 RISER # 6	Mon	2.123	Pass	
1ST FLOOR WATERFLOW 2-124 RISER # 7 GYM	Mon	2.124	N/T	YELLOW TAG

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
1ST FLOOR TAMPER VALVE 2-125 RISER # 7	Mon	2.125	Pass	
1ST FLOOR WATERFLOW 2-126 RISER # 8	Mon	2.126	N/T	YELLOW TAG
1ST FLOOR TAMPER VALVE 2-127 RISER # 8	Mon	2.127	Pass	
1ST FLOOR PULL STATION 2-111 EAST EXIT BY STAGE	Mon	2.128	Pass	
1ST FLOOR PULL STATION 2-129 BAND ROOM WEST EXIT	Mon	2.129	Pass	
1ST FLOOR PULL STATION 2-130 W EXIT BY BAND ROOM	Mon	2.130	Pass	
1ST FLOOR PULL STATION 2-131 CHOIR ROOM EXIT	Mon	2.131	Pass	
1ST FLOOR PULL STATION 2-132 AUDITORIUM EXIT	Mon	2.132	Pass	
1ST FLOOR PULL STATION 2-107 SOUTH EXIT BY GYM	Mon	2.133	Pass	
1ST FLOOR PULL STATION 2-134 KITCHEN DOCK STORAGE	Mon	2.134	Pass	
1ST FLOOR PULL STATION 2-135 KITCHEN DOCK ENTRY	Mon	2.135	Pass	
1ST FLOOR BPS PNL # 8 2-136 ELEC ROOM # E 16.0	Mon	2.136	Pass	
1ST FLOOR BPS PNL # 9 2-137 ELEC ROOM # E 16.0	Mon	2.137	Pass	
1ST FLOOR BPS PNL # 6 2-138 ELEC ROOM # E 14.0	Mon	2.138	Pass	
1ST FLOOR BPS PNL # 7 2-139 ELEC ROOM # M 15.2	Mon	2.139	Pass	
2ND FLOOR SMOKE DETECTOR 1-1	Photo	1.1	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
BOOK STORAGE 2303				
2ND FLOOR SMOKE DETECTOR 1-2 BY S. BOOK STORAGE	Photo	1.2	Pass	
2ND FLOOR SMOKE DETECTOR 1-3 HALL BY CLASS 2235	Photo	1.3	Pass	
2ND FLOOR SMOKE DETECTOR 1-4 HALL BY CLASS 2235	Photo	1.4	Pass	
2ND FLOOR SMOKE DETECTOR 1-5 HALL BY ELEVATOR RM	Photo	1.5	N/T	NOT TESTED FOR RECALL
2ND FLOOR SMOKE DETECTOR 1-6 HALL BY CLASS 2232	Photo	1.6	Pass	
2ND FLOOR HEAT DETECTOR 1-7 INSIDE ELEV RM E23	Thrml	1.7	Pass	
2ND FLOOR SMOKE DETECTOR 1-8 INSIDE ELEV RM E 23	Photo	1.8	Pass	
2ND FLOOR HEAT DETECTOR 1-9 TOP OF ELEVATR SHAFT	Thrml	1.9	N/T	NOT TESTED
2ND FLOOR SMOKE DETECTOR 1-10 TOP OF ELEVATR SHAFT	Photo	1.10	N/T	NOT TESTED
2ND FLOOR SMOKE DETECTOR 1-11 AT ELEVATOR LOBBY	Photo	1.11	Pass	
2ND FLOOR SMOKE DETECTOR 1-12 TOP OF CAFE' STAIRS	Photo	1.12	Pass	
2ND FLOOR SMOKE DETECTOR 1-13 LIBRARY-EAST SIDE	Photo	1.13	Pass	
2ND FLOOR SMOKE DETECTOR 1-14 LIBRARY-EAST SIDE	Photo	1.14	Pass	
2ND FLOOR SMOKE DETECTOR 1-15 LIBRARY EAST SIDE	Photo	1.15	Pass	
2ND FLOOR SMOKE DETECTOR 1-16 LIBRARY MIDDLE AREA	Photo	1.16	Pass	
2ND FLOOR SMOKE DETECTOR 1-17 LIBRARY MIDDLE AREA	Photo	1.17	Pass	
2ND FLOOR	Photo	1.18	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
SMOKE DETECTOR 1-18 LIBRARY MIDDLE AREA				
2ND FLOOR SMOKE DETECTOR 1-19 MAIN HALL BY AUD	Photo	1.19	Pass	
2ND FLOOR SMOKE DETECTOR 1-20 MAIN HALL BY AUD	Photo	1.20	Pass	
2ND FLOOR DUCT SMOKE 1-21 LIBRARY MECH RM-AHU1	Photo	1.21	Pass	
2ND FLOOR DUCT SMOKE 1-22 LIBRARY MECH RM-AHU5	Photo	1.22	Pass	
2ND FLOOR SMOKE DETECTOR 1-23 MAIN HALL BY AUD	Photo	1.23	Pass	
2ND FLOOR DUCT SMOKE 1-24 LIBRARY MECH RM-AHU1	Photo	1.24	Pass	
2ND FLOOR SMOKE DETECTOR 1-25 LIBRARY COMPUTER LAB	Photo	1.25	Pass	
2ND FLOOR SMOKE DETECTOR 1-26 LIBRARY WEST SIDE	Photo	1.26	Pass	
2ND FLOOR SMOKE DETECTOR 1-27 LIBRARY WEST SIDE	Photo	1.27	Pass	
2ND FLOOR SMOKE DETECTOR 1-28 LIBRARY WEST SIDE	Photo	1.28	Pass	
2ND FLOOR SMOKE DETECTOR 1-29 TOP OF S/W STAIRS	Photo	1.29	Pass	
2ND FLOOR SMOKE DETECTOR 1-30 HALL BY S/W STAIRS	Photo	1.30	Pass	
2ND FLOOR SMOKE DETECTOR 1-31 BOYS REST ROOM 2251	Photo	1.31	Pass	
2ND FLOOR SMOKE DETECTOR 1-32 GIRLS REST ROOM 2249	Photo	1.32	Pass	
2ND FLOOR SMOKE DETECTOR 1-33 S/W BOYS REST ROOM	Photo	1.33	Pass	
2ND FLOOR SMOKE DETECTOR 1-34 HALL BY CLASS 2247	Photo	1.34	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
2ND FLOOR SMOKE DETECTOR 1-35 HALL BY CLASS 2243	Photo	1.35	Pass	
2ND FLOOR SMOKE DETECTOR 1-36 HALL BY CLASS 2242	Photo	1.36	Pass	
2ND FLOOR SMOKE DETECTOR 1-37 ELECTRICAL RM E22.0	Photo	1.37	Pass	
2ND FLOOR SMOKE DETECTOR 1-38 TOP OF N/W STAIRS	Photo	1.38	Pass	
2ND FLOOR SMOKE DETECTOR 1-39 HALL BY N/W STAIRS	Photo	1.39	Pass	
2ND FLOOR SMOKE DETECTOR 1-40 HALL BY CLASS 2240	Photo	1.40	Pass	
2ND FLOOR SMOKE DETECTOR 1-41 HALL BY CLASS 2215	Photo	1.41	Pass	
2ND FLOOR SMOKE DETECTOR 1-42 HALL BY CLASS 2213	Photo	1.42	Pass	
2ND FLOOR DUCT SMOKE 1-43 HALL BY CLASS 2212	Photo	1.43	Pass	
2ND FLOOR SMOKE DETECTOR 1-44 BOOK STORAGE 2211	Photo	1.44	Pass	
2ND FLOOR SMOKE DETECTOR 1-45 BOOK STORAGE 2210	Photo	1.45	Pass	
2ND FLOOR SMOKE DETECTOR 1-46 HALL BY CLASS 2116	Photo	1.46	Pass	
2ND FLOOR SMOKE DETECTOR 1-47 HALL BY N/W OFFICES	Photo	1.47	Pass	
2ND FLOOR SMOKE DETECTOR 1-48 MEN'S RR 2220	Photo	1.48	Pass	
2ND FLOOR SMOKE DETECTOR 1-49 WOMENS RR 2221	Photo	1.49	Pass	
2ND FLOOR SMOKE DETECTOR 1-50 HALL IN OFFICE 2200	Photo	1.50	Pass	
2ND FLOOR HEAT DETECTOR 1-51	ThrmI	1.51	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
OFFICE BREAK RM 2200				
2ND FLOOR SMOKE DETECTOR 1-52 HALL IN OFFICE 2200	Photo	1.52	Pass	
2ND FLOOR SMOKE DETECTOR 1-53 HALL BY CLASS 2224	Photo	1.53	Pass	
2ND FLOOR SMOKE DETECTOR 1-54 HALL BY CLASS 2222	Photo	1.54	Pass	
2ND FLOOR SMOKE DETECTOR 1-55 IN CLASS 2235	Photo	1.55	Pass	
2ND FLOOR SMOKE DETECTOR 1-56 IN SOUND BOOTH	Photo	1.56	Pass	
2ND FLOOR DUCT SMOKE 1-88 EAST LIBRARY ENTRY	Photo	1.88	Pass	
2ND FLOOR DUCT SMOKE 1-89 WEST LIBRARY EXIT	Photo	1.89	Pass	
2ND FLOOR PRIMARY ELEV RECALL ELEVATOR EQUIP ROOM	CtrlRL	1.101	N/T	NOT TESTED
2ND FLOOR ALT. ELEV RECALL ELEVATOR EQUIP ROOM	CtrlRL	1.102	N/T	NOT TESTED
2ND FLOOR ELEVATOR SHUNT TRIP ELEVATOR EQUIP ROOM	CtrlRL	1.103	N/T	NOT TESTED
2ND FLOOR ELEV POWER LOSS ELEVATOR EQUIP ROOM	CtrlRL	1.104	N/T	NOT TESTED
2ND FLOOR BEAM DETECTOR 1-105 NORTH CAFETERIA	Mon	1.105	Pass	
2ND FLOOR BEAM DETECTOR 1-106 MIDDLE CAFETERIA	Mon	1.106	Pass	
2ND FLOOR BEAM DETECTOR 1-107 SOUTH CAFETERIA	Mon	1.107	Pass	
2ND FLOOR PULL STATION 1-108 SOUND BOOTH STAIRS	Mon	1.108	Pass	
2ND FLOOR PULL STATION 1-109 SOUTH WEST STAIRS	Mon	1.109	Pass	
2ND FLOOR	Mon	1.110	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
PULL STATION 1-110 NORTH WEST STAIRS				
2 ND FLOOR BPS PNL # 1 1-111 ELEC RM E 22.0	Mon	1.111	Pass	
2ND FLOOR MAG LOCK FOR LIBRARY HALL BY CLASS 2234	CtrlRL	1.112	Pass	
2ND FLOOR SMOKE DETECTOR 2-1 CLASSROOM 2133	Photo	2.1	Pass	
2ND FLOOR SMOKE DETECTOR 2-2 COMPUTER LAB 2134	Photo	2.2	Pass	
2ND FLOOR SMOKE DETECTOR 2-3 HALL BY COMPLAB 2132	Photo	2.3	Pass	
2ND FLOOR SMOKE DETECTOR 2-4 COMPUTER LAB 2132	Photo	2.4	Pass	
2ND FLOOR SMOKE DETECTOR 2-5 COMPUTER LAB 2125	Photo	2.5	Pass	
2ND FLOOR SMOKE DETECTOR 2-6 IDF RM-COMP LAB 2132	Photo	2.6	Pass	
2ND FLOOR SMOKE DETECTOR 2-7 COMPUTER LAB 2123	Photo	2.7	Pass	
2ND FLOOR SMOKE DETECTOR 2-8 COMPUTER LAB 2121	Photo	2.8	Pass	
2ND FLOOR SMOKE DETECTOR 2-9 HALL BY COMPLAB 2121	Photo	2.9	Pass	
2ND FLOOR SMOKE DETECTOR 2-10 HALL BY CLASS 2105	Photo	2.10	Pass	
2ND FLOOR SMOKE DETECTOR 2-11 COMPUTER LAB 2130	Photo	2.11	Pass	
2ND FLOOR SMOKE DETECTOR 2-12 HALL BY COMPLAB 2130	Photo	2.12	Pass	
2ND FLOOR SMOKE DETECTOR 2-13 BOYS RR 2107	Photo	2.13	Pass	
2ND FLOOR SMOKE DETECTOR 2-14 COMPUTER LAB 2131	Photo	2.14	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
2ND FLOOR SMOKE DETECTOR 2-15 GIRLS REST ROOM 2109	Photo	2.15	Pass	
2ND FLOOR SMOKE DETECTOR 2-16 S/E BOYS REST ROOM	Photo	2.16	Pass	
2ND FLOOR SMOKE DETECTOR 2-17 EAST EXIT ATRIUM	Photo	2.17	Pass	
2ND FLOOR SMOKE DETECTOR 2-18 TOP OF S/E STAIRS	Photo	2.18	Pass	
1ST FLOOR SMOKE DETECTOR 2-19 BOTTOM OF STAIRS # 2	Photo	2.19	Pass	
1ST FLOOR SMOKE DETECTOR 2-20 CLASSROOM 1134	Photo	2.20	Pass	
1ST FLOOR SMOKE DETECTOR 2-21 COMPLAB BY CLASS1134	Photo	2.21	Pass	
1ST FLOOR SMOKE DETECTOR 2-22 HALL BY BKSTORG 1125	Photo	2.22	Pass	
1ST FLOOR SMOKE DETECTOR 2-23 HAL BY CLASS 1124	Photo	2.23	Pass	
1ST FLOOR DUCT SMOKE 2-24 HALL BY TECHLAB 1121	Photo	2.24	Pass	
1ST FLOOR SMOKE DETECTOR 2-25 HALL BY TECHLAB 1121	Photo	2.25	Pass	
1ST FLOOR SMOKE DETECTOR 2-26 ELECTRICAL RM E11.0	Photo	2.26	Pass	
1ST FLOOR HEAT DETECTOR 2-27 HOME ECON RM 1122	Thrml	2.27	Pass	
1ST FLOOR SMOKE DETECTOR 2-28 TECH LAB 1120	Photo	2.28	Pass	
1ST FLOOR SMOKE DETECTOR 2-29 HALL BY TECHLAB 1120	Photo	2.29	Pass	
1ST FLOOR SMOKE DETECTOR 2-30 S/E TECH LAB 1120	Photo	2.30	Pass	
1ST FLOOR SMOKE DETECTOR 2-31	Photo	2.31	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
S/E TECH LAB 1120				
1ST FLOOR SMOKE DETECTOR 2-32 S/E TECH LAB 1120	Photo	2.32	Pass	
1ST FLOOR SMOKE DETECTOR 2-33 S/E TECH LAB 1120	Photo	2.33	Pass	
1ST FLOOR SMOKE DETECTOR 2-34 PORTABLE #1	Photo	2.34	Pass	
1ST FLOOR SMOKE DETECTOR 2-35 PORTABLE #2	Photo	2.35	Pass	
1ST FLOOR SMOKE DETECTOR 2-36 PORTABLE #5	Photo	2.36	Pass	
1ST FLOOR SMOKE DETECTOR 2-37 PORTABLE #3	Photo	2.37	Pass	
1ST FLOOR SMOKE DETECTOR 2-38 PORTABLE #4	Photo	2.38	Pass	
1ST FLOOR SMOKE DETECTOR 2-39 PORTABLE #6	Photo	2.39	Pass	
1ST FLOOR SMOKE DETECTOR 2-40 PORTABLE #7	Photo	2.40	Pass	
1ST FLOOR SMOKE DETECTOR 2-41 PORTABLE #8	Photo	2.41	Pass	
1ST FLOOR SMOKE DETECTOR 2-42 PORTABLE - RAC	Photo	2.42	Pass	
1ST FLOOR SMOKE DETECTOR 2-43 PORTABLE #11	Photo	2.43	Pass	
1ST FLOOR SMOKE DETECTOR 2-44 PORTABLE #12	Photo	2.44	Pass	
1ST FLOOR SMOKE DETECTOR 2-45 PORTABLE #9	Photo	2.45	Pass	
1ST FLOOR SMOKE DETECTOR 2-46 PORTABLE #10	Photo	2.46	Pass	
1ST FLOOR SMOKE DETECTOR 2-47 PORTABLE #13	Photo	2.47	Pass	
1ST FLOOR	Photo	2.48	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
SMOKE DETECTOR 2-48 PORTABLE #14				
1ST FLOOR SMOKE DETECTOR 2-49 PORTABLE #15	Photo	2.49	Pass	
1ST FLOOR SMOKE DETECTOR 2-50 PORTABLE #16	Photo	2.50	Pass	
1ST FLOOR SMOKE DETECTOR 2-51 PORTABLE #17	Photo	2.51	Pass	
1ST FLOOR SMOKE DETECTOR 2-52 PORTABLE #18	Photo	2.52	Pass	
1ST FLOOR SMOKE DETECTOR 2-53 BOTTOM OF STAIRS # 1	Photo	2.53	Pass	
1ST FLOOR SMOKE DETECTOR 2-54 EXIT BY STAIRS # 1	Photo	2.54	Pass	
2ND FLOOR SMOKE DETECTOR 2-55 TOP OF STAIRS # 1	Photo	2.55	Pass	
2ND FLOOR SMOKE DETECTOR 2-56 HALL BY STAIRS # 1	Photo	2.56	Pass	
2ND FLOOR SMOKE DETECTOR 2-57 HALL BY CLASS 2101	Photo	2.57	Pass	
2ND FLOOR SMOKE DETECTOR 2-58 HALL BY CLASS 2102	Photo	2.58	Pass	
2ND FLOOR SMOKE DETECTOR 2-59 HALL BY CLASS 2111	Photo	2.59	Pass	
2ND FLOOR SMOKE DETECTOR 2-60 HALL BY CLASS 2114	Photo	2.60	Pass	
2ND FLOOR SMOKE DETECTOR 2-61 ELECTRICAL RM E 21.0	Photo	2.61	Pass	
2ND FLOOR SMOKE DETECTOR 2-62 BOOK STORAGE 2122	Photo	2.62	Pass	
2ND FLOOR SMOKE DETECTOR 2-63 HALL BY E BOOK STRGE	Photo	2.63	Pass	
2ND FLOOR SMOKE DETECTOR 2-64 HALL BY COMPLAB 2125	Photo	2.64	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
2ND FLOOR SMOKE DETECTOR 2-65 GIRLS REST RM 2201	Photo	2.65	Pass	
2ND FLOOR SMOKE DETECTOR 2-66 BOYS REST RM 2203	Photo	2.66	Pass	
2ND FLOOR SMOKE DETECTOR 2-67 TOP OF MIDDLE STAIRS	Photo	2.67	Pass	
2ND FLOOR SMOKE DETECTOR 2-68 HALL BY MIDDLE STAIR	Photo	2.68	Pass	
2ND FLOOR SMOKE DETECTOR 2-69 HALL BY MIDDLE STAIR	Photo	2.69	Pass	
2ND FLOOR SMOKE DETECTOR 2-70 HALL BY COMPLAB 2134	Photo	2.70	Pass	
2ND FLOOR SMOKE DETECTOR 2-71 SOUTH ELECTRICAL RM	Photo	2.71	Pass	
2ND FLOOR HEAT DETECTOR 2-72 S/E SHOP AIR COMP RM	Thrml	2.72	Pass	
2ND FLOOR PULL STATION 2-101 TOP OF S/E STAIRS	Mon	2.101	Pass	
1ST FLOOR PULL STATION 2-102 EXIT BY TECHLAB 1120	Mon	2.102	Pass	
1ST FLOOR PULL STATION 2-103 S/E TECH LAB	Mon	2.103	Pass	
1ST FLOOR PULL STATION 2-104 S/E SHOP BY TECHLAB	Mon	2.104	Pass	
1ST FLOOR PULL STATION 2-105 EXIT BY N/E STAIRS	Mon	2.105	Pass	
1ST FLOOR PULL STATION 2-106 BOTTOM OF N/E STAIRS	Mon	2.106	Pass	
2ND FLOOR PULL STATION 2-107 TOP OF N/E STAIRS	Mon	2.107	Pass	
2ND FLOOR PULL STATION 2-108 TOP OF MIDDLE STAIRS	Mon	2.108	Pass	
1ST FLOOR PAINT HOOD 1-109	Mon	2.109	N/T	NOT TESTED

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
S/E SHOP BY TECHLAB				
1ST FLOOR BPS PNL #5 2-110 ELEC RM E 11.0	Mon	2.110	Pass	
2 ND FLOOR BPS PNL # 3 2-111 ELEC RM E 21.0	Mon	2.111	Pass	
2 ND FLOOR BPS PNL # 2 2-112 ELEC RM E 23.0	Mon	2.112	Pass	
1ST FLOOR BPS PNL # 4 2-113 ELEC RM E 11.0	Mon	2.113	Pass	
FIELD HOUSE SMOKE DETECTOR 1-1 ABOVE FIRE PANEL	Photo	1.1	Pass	
FIELD HOUSE HEAT DETECTOR 1-2 LAUNDRY RM #1702	Thrml	1.2	Pass	
FIELD HOUSE HEAT DETECTOR 1-3 DRESSING RM#1703 RR	Thrml	1.3	Pass	
FIELD HOUSE HEAT DETECTOR 1-4 DRESSING RM#1705 RR	Thrml	1.4	Pass	
FIELD HOUSE HEAT DETECTOR 1-5 BOY'S COACH'S RESTRM	Thrml	1.5	Pass	
FIELD HOUSE SMOKE DETECTOR 1-6 HALL BY TRAINING RM	Photo	1.6	Pass	
FIELD HOUSE HEAT DETECTOR 1-7 OUTSIDE MECH RM 170	Thrml	1.7	Pass	
FIELD HOUSE HEAT DETECTOR 1-8 OUTSIDE MECH RM 1716	Thrml	1.8	Pass	
FIELD HOUSE HEAT DETECTOR 1-9 MOWER STORAGE RM	Thrml	1.9	Pass	
FIELD HOUSE HEAT DETECTOR 1-10 DRESSING RM#1709 RR	Thrml	1.10	Pass	
FIELD HOUSE SMOKE DETECTOR 1-11 BOYS OUTSIDE RR#1712	Photo	1.11	Pass	
FIELD HOUSE	Photo	1.12	Pass	

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
SMOKE DETECTOR 1-12 GIRLS OUTSIDE RR#1713				
FIELD HOUSE HEAT DETECTOR 1-13 DRESSING RM#1711 RR	Thrml	1.13	Pass	
FIELD HOUSE HEAT DETECTOR 1-14 GIRLS COACH'S RESTRM	Thrml	1.14	Pass	
FIELD HOUSE SMOKE DETECTOR 1-15 HALL BY STORAG 1170A	Photo	1.15	Pass	
FIELD HOUSE SMOKE DETECTOR 1-16 HALL BY STORAG 1711A	Photo	1.16	Pass	
FIELD HOUSE SMOKE DETECTOR 1-17 ELECTRICAL RM #1700	Photo	1.17	Pass	
FIELD HOUSE SMOKE DETECTOR 1-18 JANITORS RM #1701	Photo	1.18	Pass	
FIELD HOUSE SMOKE DETECTOR 1-19 BOYS OUTSIDE RR#1712	Photo	1.19	Pass	
FIELD HOUSE DUCT SMOKE 1-20 LAUNDRY RM #1702	Photo	1.20	Pass	
FIELD HOUSE DUCT SMOKE 1-21 VIDEO RM #1706	Photo	1.21	Pass	
FIELD HOUSE DUCT SMOKE 1-22 HALL BY STORAG 1170A	Photo	1.22	Pass	
FIELD HOUSE DUCT SMOKE 1-23 HALL BY STORAG 1711A	Photo	1.23	Pass	
FIELD HOUSE HEAT DETECTOR 1-24 JAN STORAGE 1712	Thrml	1.24	Pass	
FIELD HOUSE PULL STATION 1-101 NORTH EXIT	Mon	1.101	Pass	
FIELD HOUSE PULL STATION 1-102 EAST EXIT	Mon	1.102	Pass	
FIELD HOUSE PULL STATION 1-103 SOUTH EAST EXIT	Mon	1.103	Pass	
FIELD HOUSE WATERFLOW 1-104 RISER IN JANITORS RM	Mon	1.104	Pass	22 SECONDS

Rowlett H/S Points List

10/29/2018

Description	Type	Address	Pass/Fail	Remarks
FIELD HOUSE TAMPER VALVE 1-105 RISER IN JANITORS RM	Mon	1.105	Pass	
FIELD HOUSE PULL STATION 1-106 WEST EXIT	Mon	1.106	Pass	
FIELD HOUSE BPS PNL # 1 1-107 JAN ROOM 1701	Mon	1.107	Pass	

REPORT OF INSPECTION

Additional Observations & Comments

10/29/2018

1 Tested as installed.

2 Batteries tested by GISD.

3

4

5

6

7

8

9

10